



QUARTZ | GRANITE | MARBLE | SLATE | TRAVERTINE | PORCELAIN | L.V.T. | MOSAICS

DISCLAIMER FOR QUARTZ & OTHER STONE PRODUCTS

SILICA DUST HAZARD:

SILICA DUST CAUSES SEVERE ILLNESS, CANCER AND DEATH DUST PARTICLES ARE INVISIBLE Always wear a NIOSH certified air supplied respirator WET cutting, drilling, milling, polishing, blasting ONLY Always cut, drill, mill, polish, blast in well-ventilated areas Wet clean up only | Wet Sweeping only Dust on your clothes is dangerous to you and people at home Dust on your clothes is invisible Remove and wash work clothes on your work site Wash your skin thoroughly You are responsible for your work environment Do an environmental assessment Take a respirable crystalline silica safety awareness course Ask your doctor about Silica exposure monitoring Always make sure all OSHA, NIOSH standards and regulations are strictly followed.

INSPECTION:

Inspect the material for overall condition and appearance prior to fabrication. Things to look for: color| shade match| surface quality |Scratches |slab thickness |Blemishes |any other irregularity. Slabs should be stored indoors and should not be exposed to Sunlight.

Head Office: 3936 E Coronado St. Anaheim, CA 92807 Mailing: 1285 N Fairbury Lane Anaheim Hills, CA 92807
Ph # 714.777.9323 Fax # 714.844.9101 Email: info@niditec.com Website: www.niditec.com



Albuquerque, NM



Anaheim, CA



Denver, CO



Salt Lake City, UT